



GARY R. HERBERT
Governor
SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Minerals Inspection Report

Reviewed

[Signature]

Report Date: **June 29, 2016**

Mine Name: BHT Mine	Permit Number: S005/0003	Mine Status: Active
Operator Name: Pisgah Rock Products	Inspection Date: 06/28/2016	Permit Fees: Paid
Inspector(s): Lynn Kunzler	Inspection Time: 2:30 pm	Bond Amount: \$29,500
Attendee(s): Zeb Reay	Weather: clear/warm	Bond Escalation: 5/31/2019
Inspection Purpose: Routine inspection		Prior Inspection: 05/18/2015

Conclusions and Recommendations

The Site is apparently in compliance at this time. Continue to conduct routine inspections when in the area.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Permit fees are current. The Operator's name has recently changed on this project from Pisgah Grazing, Inc. to Pisgah Rock Products, Inc.		
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
This site is gated to prevent unauthorized access when the mine is not in operation. The scale house keeper, located just inside the gate, keeps tabs on those entering during operating hours. The site was free of trash and debris.		
3. <i>Protection of Drainages/Erosion Control</i>	<input type="checkbox"/>	<input type="checkbox"/>
4. <i>Deleterious Material</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Fuel is contained in a double-walled tank, which meets fire-marshall secondary containment requirements.		
5. <i>Roads (maintenance, surfacing, dust control, safety)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
They were in the process of maintaining the road, preparing the surface for an application of mag chloride to control dust.		
6. <i>Reclamation</i>	<input type="checkbox"/>	<input type="checkbox"/>
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i>	<input type="checkbox"/>	<input type="checkbox"/>
8. <i>Soils</i>	<input type="checkbox"/>	<input type="checkbox"/>
9. <i>Revegetation</i>	<input type="checkbox"/>	<input type="checkbox"/>
10. <i>Other</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
This area is infested with Dyer's Woad, a noxious weed. The operator has been diligent in control efforts. There is a noticeable reduction in the amount of this species since my last inspection,		

Inspector's Signature: *[Signature]*

CC: Operator

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M005-Cache/S050003-BHT Mine/inspections/insp-06282016.pdf



